DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-022241 Address: 333 Burma Road **Date Inspected:** 23-Mar-2011

City: Oakland, CA 94607

OSM Arrival Time: 1500 **Project Name:** SAS Superstructure **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Mike Hasler was present during the times noted above for observations and testing relative to the work being performed.

Bay 1

This QA inspector observed ZPMC in process of SMAW weld repair (WR20481) welding on traveler rail 20TR2-044- assembly. ZPMC CWI Huang Min was present at this time of this observation and informed this QA inspector of the work that is in process. It was stated that ZPMC had 2 welders and identified the welders by ZPMC welder identification number appointed to then by ZPMC. This QA inspector verified this information for the following location;

WR20481

Weld-20TR2-044-011, 013 WPS-345-SMAW-1G(1F)-Repair Welder- 049769 1G/SMAW/CJP

WR20481

Weld- 20TR2-036-011

WPS-345-SMAW-1G(1F)-Repair

Welder- 054467 1G/SMAW/CJP



WELDING INSPECTION REPORT

(Continued Page 2 of 2)

The following digital picture illustrates welding traveler rail 20TR2-044- weld repair.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

"As noted within the contents of this report."

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 1500026784, who represents the Office of Structural Materials for your project.

Inspected By:	Hasler,Mike	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer